

NAVIGATION WARNING NOTICE TO MARINERS No. 05-2025 (T)


OWNERS, MANAGERS, OPERATORS, SKIPPERS, AND MASTERS OF ALL VESSELS OPERATING WITHIN THE VINCINITY OF GUANA ISLAND TO SCRUB ISLAND, SOUTH OF GREAT CAMANOE ISLAND.

REFERENCE:

REPORTED INCIDENT OF NAVIGATIONAL BUOY BREAKAWAY

LOCATION:

LONG BAY, BEEF ISLAND, BRITISH VIRGIN ISLANDS VG 18-27.194N 064-32.365W



Mariners are advised that the **Long Bay North Cardinal Marker**, which marks a **submerged rock**, has broken free from its station and is currently **missing from its charted position**.

The buoy marks the rock located at the coordinates:

Latitude 18°27.194'N, Longitude 64°32.'W

This cardinal mark is a critical aid to navigation, marking the presence of a submerged hazard in the long bay area. The absence of this buoy poses a **significant risk to safe navigation**, particularly in low visibility or for vessels unfamiliar with local waters. All mariners are urged to:

- Exercise extreme caution when navigating in this area, and
- **Keeping safely North** of the charted coordinates of the north cardinal maker.

Efforts are currently underway to recover and re-establish the buoy. A follow-up notice will be issued once this navigation aid is restored.

This notice has been issued in accordance with section 163 of the Merchant Shipping Act, 2001

Mr. John Samuel
Director of Shipping
Virgin Islands Shipping & Maritime Authority
1st Floor, Ritter House
Wickham's Cay II, Tortola
British Virgin Islands VG 1110

16th December 2025