



Virgin Islands Shipping & Maritime Authority

NAVIGATION WARNING **NOTICE TO MARINERS No. 06-2026 (T)**


OWNERS, MANAGERS, OPERATORS, SKIPPERS, AND MASTERS OF ALL VESSELS OPERATING IN AND AROUND TRELLIS BAY, BEEF ISLAND

REFERENCE:

TRELLIS BAY (SPRAT POINT) NORTH CARDINAL MARKER NOT ON STATION

LOCATION:

TRELLIS BAY (SPRAT POINT), BEEF ISLAND (— CHARTED LOCATION OF THE NORTH CARDINAL MARKER: 18° 27.095' N, 064° 31.767' W)



Mariners are advised that the **Trellis Bay North Cardinal Marker** is currently not on station and should not be relied upon as an aid to navigation in the area.

All mariners operating in Trellis Bay and its approaches are urged to **exercise extreme caution**, maintain a proper lookout, proceed at a safe speed, and navigate using all available means appropriate to the prevailing circumstances.

Navigational Warning NTM 06-2026 (T)

Mariners should keep well clear of the navigational hazards in the vicinity, monitor local marine communications for safety updates, and comply promptly with any directions issued by the relevant authorities.

This notice has been issued in accordance with section 163 of the Merchant Shipping Act, 2001

Mr. John Samuel
Managing Director
Virgin Islands Shipping & Maritime Authority
1st Floor, Ritter House
Wickham's Cay II, Tortola
British Virgin Islands VG 1110

12th October 2026