



Virgin Islands Shipping Registry

Ritter House, PO Box 4751, Wickham's Cay II, Tortola, British Virgin Islands, VG1110
Tel: +1 284 468 2902/2903 • Fax: +1 284 468 2913 • Duty Officer: +1 284 468 9646
Website: www.vishipping.gov.vg • General Email: vishipping@gov.vg

NAVIGATIONAL WARNING

NOTICE TO MARINERS No.3 - 2021

OWNERS, MANAGERS, OPERATORS, SKIPPERS AND MASTERS OF ALL VESSELS OPERATING ON THE SIR FRANCIS DRAKE CHANNEL.

REFERENCE: EXTINGUISHED SOUTH CARDINAL BUOY, BEEF ISLAND BLUFF, SIR FRANCIS DRAKE CHANNEL.

The South Cardinal Buoy at the Beef Island Bluff (Lat:18° 25.539'N – Long: 064° 31.322'W), has been reported extinguished. Mariners are advised to maintain a sharp lookout, and to exercise caution when navigating the Sir Francis Drake Channel, particularly during periods of restricted visibility, and at nighttime.

This notice has been issued in accordance with section 163 of the Merchant Shipping Act, 2001.

Mr. John Samuel
Director of Shipping
Virgin Islands Shipping Registry
Ritter House
Wickham's Cay II, Tortola
British Virgin Islands VG 1110

24th March 2021