



Virgin Islands Shipping Registry

1st Floor Ritter House • Wickham's Cay II

Road Town • Tortola • Virgin Islands VG1110 Cell: 284-468-9646

Website: www.bvimaritime.vg • Email: vishipping@bvimaritime.vg

NAVIGATIONAL WARNING

NOTICE TO MARINERS No.6 - 2021

OWNERS, MANAGERS, OPERATORS, SKIPPERS AND MASTERS OF ALL VESSELS OPERATING IN THE PASSAGE BETWEEN LITTLE CAMANOE AND CONCH BAY, BEEF ISLAND.

REFERENCE: EXTINGUISHED NORTH CARDINAL BUOY, LITTLE CAMANOE PASSAGE CONCH BAY, BEEF ISLAND.

The North Cardinal Buoy at Little Camanoe Passage Conch Bay, Beef Island. (Lat:18° 27.194'N – Long: 064° 32.365'W), has been reported extinguished. Mariners are advised to maintain a sharp lookout, and to exercise caution when navigating the passage between Little Camanoe and Conch Bay, Beef Island, particularly during periods of restricted visibility, and at nighttime.

This notice has been issued in accordance with section 163 of the Merchant Shipping Act, 2001.

Mr. John Samuel
Director of Shipping
Virgin Islands Shipping Registry
Ritter House
Wickham's Cay II, Tortola
British Virgin Islands VG 1110



27th August 2021