



Virgin Islands Shipping Registry

Ritter House, PO Box 4751, Road Town, Tortola, British Virgin Islands, VG1110
Tel: +1 284 468 2902/2903 • Fax: +1 284 468 2913 • Duty Officer: +1 284 468 9646
Website: www.vishipping.gov.vg • General Email: vishipping@bvimaritime.vg

NOTICE TO MARINERS No.2 - 2022

OWNERS, MANAGERS, OPERATORS, SKIPPERS AND MASTERS OF ALL VESSELS OPERATING IN THE VICINITY OF TRELIS BAY, BEEF ISLAND.

REFERENCE:

THE BVIAA HAS ESTABLISHED A NO ANCHORING ZONE (RESTRICTED AREA) IN THE WATERS ALONG AND ON EITHER SIDE OF AN IMAGINARY EXTENDED CENTERLINE OF THE EASTERN RUNWAY THRESHOLD. THE RESTRICTED AREA IS BOUNDED BY THE FOLLOWING COORDINATES:

- A. 18° 26.9' N 64° 32.1' W**
- B. 18° 27.0' N 64° 32.1' W**
- C. 18° 27.1' N 64° 31.9' W**
- D. 18° 27.0' N 64° 31.9' W**



VESSELS WITH AN AIR DRAFT OF 50FT OR MORE MUST CONTACT THE BEEF ISLAND CONTROL TOWER ON MARINE VHF CH. 16, DURING OPERATIONAL HOURS OF THE AIRPORT, FOR PERMISSION TO TRANSIT THE NO ANCHORING ZONE (RESTRICTED AREA).





Virgin Islands Shipping Registry

Ritter House, PO Box 4751, Road Town, Tortola, British Virgin Islands, VG1110

Tel: +1 284 468 2902/2903 • Fax: +1 284 468 2913 • Duty Officer: +1 284 468 9646

Website: www.vishipping.gov.vg • General Email: vishipping@bvimaritime.vg

Mariners should exercise caution when navigating the approaches to Trellis Bay, Beef Island.

This notice has been issued in accordance with section 163 of the Merchant Shipping Act, 2001

Mr. John Samuel
Director of Shipping
Virgin Islands Shipping Registry
Ritter House
Wickham's Cay II, Tortola
British Virgin Islands VG 1110