



# Virgin Islands Shipping & Maritime Authority

## **NAVIGATION WARNING** **NOTICE TO MARINERS No. 03-2026 (T)**

**OWNERS, MANAGERS, OPERATORS, SKIPPERS, AND MASTERS OF ALL VESSELS OPERATING IN AND AROUND TRELIS BAY, BEEF ISLAND**

**REFERENCE:**

**CHANNEL MARKER LANTERN MISSING**

**LOCATION:**

**TRELIS BAY ENTRANCE CHANNEL : TRELIS BAY RED (1) 18 26.783' N. 064 31.967' W**



Mariners are advised that the **last Red Entrance Channel Marker at Trellis Bay is missing its lantern.**

This marker forms part of the preferred channel entrance to the Trellis Bay docks and mooring field.

All mariners are urged to **exercise extreme caution** when navigating in this area and to maintain a proper lookout when transiting the channel, particularly at night.

Navigational Warning NTM 01-2026 (T)

This notice has been issued in accordance with section 163 of the Merchant Shipping Act, 2001

Mr. John Samuel  
Director of Shipping  
Virgin Islands Shipping & Maritime Authority  
1<sup>st</sup> Floor, Ritter House  
Wickham's Cay II, Tortola  
British Virgin Islands VG 1110

11<sup>th</sup> Mar 2026