VIRGIN ISLANDS SHIPPING & MARITIME AUTHORITY

NAVIGATION WARNING

NOTICE TO MARINERS No. 07-2026 (T)

GORDA SOUND CHANNEL ENTRANCE RED MARKER DAMAGED


OWNERS, MANAGERS, OPERATORS, SKIPPERS, AND MASTERS OF ALL VESSELS OPERATING IN AND AROUND GORDA SOUND, VIRGIN GORDA

REFERENCE:

DAMAGED AID TO NAVIGATION - GORDA SOUND CHANNEL ENTRANCE RED MARKER

POSITION

18°30.729'N 64°22.858'W



The Red Lateral Marker at the Gorda Sound entrance, Virgin Gorda (18°30.729'N 64°22.858'W), has been reported damaged. **Its position and navigational characteristics may be unreliable.**

Navigational Warning NTM 07-2026 (T)

Vessels in the vicinity are urged to navigate with **extreme caution**, maintain a proper lookout, proceed at a safe speed, and use all available means, including updated charts, GPS, radar, depth sounder, and visual observation.

Take particular care during periods of darkness or restricted visibility. This Notice is issued in accordance with Section 163 of the Merchant Shipping Act, 2001.

Mr. John Samuel
Managing Director
Virgin Islands Shipping & Maritime Authority
1st Floor, Ritter House
Wickham's Cay II, Tortola
British Virgin Islands VG 1110

4 November 2026